

IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS


WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.

CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save

for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that the power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel.


These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

SPHERE PENDANTS - CABLE SUSPENSION



NOTE: If Light Engine is shipped separate from Sphere, assembly fixture as shown. Secure Sphere Cover with Screws.


CAA



CAA Mounting Instructions (REMOTE POWER SUPPLY)

1. Attach Cross Bar to J-Box with screws (by others.)
2. Cut Cord to desired length and strip ends. Feed Cord through Canopy and place Strain Relief on Cord. Complete wiring per local code.
3. Secure Canopy to Cross Bar with Cable Gripper. Feed Cable through Cable Gripper and adjust fixture height. Cut excess Cable.

PSA



PSA Mounting Instructions (CANOPY MOUNTED POWER SUPPLY)

1. Attach Hanger Plate to J-Box with screws (by others.)
2. Feed Cable through Canopy and insert into Cable Gripper. Adjust fixture height.
3. Feed Cord through Canopy, Cut Cord to desired length, strip ends, and place Strain Relief on Cord. Complete wiring per local code.
4. Secure Canopy to Hanger Plate by aligning studs from Canopy to receptacles on Hanger Plate. Push Canopy to engage receptacles until flush with ceiling.

8/16/23

IS114884X